

ExxonMobil Pipeline Company
52 Beacham Street
Everett, MA
Phone: (617) 381-2802
Facsimile: (617) 381-2954

Damian Guzman
Terminal Superintendent



June 6, 2014

Water Technical Unit (SMR-04)
U.S. Environmental Protection Agency
5 Post Office Square – Suite 100
Boston, Massachusetts 02109-3912

RE: Submission of Discharge Monitoring Reports
Permit No. MA0000833

Dear Sir/Madam:


This report is being submitted on behalf of ExxonMobil Oil Corporation. The May 2014 sampling data has been submitted via the NetDMR system to the US EPA including the permit-required analytical reports for these periods:

- May 1-31, 2014 Monthly DMR Period
 - Sampled from outfall 01A on May 17, 22, and 27, 2014
 - No discharge from outfall 01B
 - Sampled from outfall 01C on May 8, 2014

During this sampling period, an exceedance occurred on outfall 01A for Total Suspended Solids (TSS). The monthly average for this parameter resulted in 34.1 mg/L versus the monthly permit limit of 30 mg/L. Two TSS samples from May 17, 2014 were analyzed yielding the reported value of 88.1 mg/L. One sample on each of two additional dates (6.21 mg/L on May 22, 2014 and 8.00 mg/L on May 27, 2014) yielded a monthly average of 34.1 mg/L. The follow-up sampling from the two later dates yielded results below permit limits. In order to prevent reoccurrence, the Everett Terminal enhanced sediment control measures in the tank farm during the week of June 2, 2014.

If you have any questions, please contact me at (617) 381-2802.

Sincerely,



Damian Guzman
Terminal Superintendent

cc: Mass. Dept. of Environmental Protection, Division of Watershed Management –Surface Water
Discharge Permit Program
Mass. Dept. of Environmental Protection, Northeast Regional Office-Bureau of Waste Prevention

An ExxonMobil Subsidiary